

287

BOEING REALTY CORPORATION FORMER C-6 FACILITY LOS ANGELES, CALIFORNIA

REQUEST FOR WELL CLOSURE

GROUNDWATER MONITORING WELL TMW-16

To: Mr. Brian Mossman

Boeing Realty Corporation 3855 Lakewood Blvd.

Building 1A MC D001-0097 Long Beach, CA 90846

From: Haley & Aldrich, Inc.

Date: January 7, 2003

Re: Request for Closure, Groundwater Monitoring Well TMW-16, Boeing Realty Corporation, Former

C-6 Facility, Los Angeles, California

Introduction

Haley & Aldrich, Inc. is herein providing this request to close groundwater monitoring well TMW-16. Groundwater monitoring well TMW-16 is located along the western boundary of Parcel C, north of Knox Street, on the Boeing Realty Corporation's (BRC's) Former C-6 Facility in Los Angeles, California (Site). The Site location is shown on Figure 1 and groundwater monitoring well TMW-16 is shown on Figure 2.

Background

Groundwater monitoring well TMW-16 was installed on January 29, 1999, by Kennedy/Jenks Consultants as part of a Site-wide groundwater monitoring program. The purpose of groundwater monitoring well TMW-16 was to facilitate sampling and measurement of groundwater conditions at the top of the Bellflower Aquitard and is not part of the planned groundwater bioremediation monitoring program. Groundwater monitoring well TMW-16 is constructed of 2-inch diameter Schedule-40 PVC screen and casing, extended to a depth of approximately 81.5 feet, and has a screened interval from approximately 61.5 to 81.5 feet below ground surface (bgs). The present screened interval and total depth of TMW-16 differ from the attached well construction log due to site grading activities conducted in 2001. Site grade was raised approximately six feet from the original grade. The casing of TMW-16 was subsequently extended to match the current site grade. The measured depth to groundwater in TMW-16 was 68.4 feet bgs on September 16, 2002.

Groundwater monitoring well TMW-16 has been sampled 7 times including the most recent sampling on September 16, 2002. Trichloroethene (TCE) is the primary constituent present, and concentrations have been steadily declining from the initial sampling event in 1999 (4.5 ug/l) to the most recent sampling event in September 2002 (1.7 ug/l).



PROPOSED WELL CLOSURE PROCEDURE

The closure of groundwater monitoring well TMW-16 will proceed as follows:

- 1. **Permit** Prior to drilling activities, a permit will be obtained from the Los Angeles County Department of Health Services for the closure of groundwater monitoring well TMW-16.
- 2. **Groundwater Level Measurement** Measure the depth to groundwater in the well from the top of casing using an electronic water level indicator. The measurement will be recorded in the field log.
- 3. **Groundwater Sampling** Groundwater monitoring well TMW-16 was recently sampled on September 16, 2002 as part of the Site-wide semi-annual groundwater monitoring event. Sampling was performed in accordance with the Regional Water Quality Control Board-Los Angeles Region (RWQCB-LA)-approved Groundwater Monitoring Workplan-2002, Boeing Realty Corporation, Former C-6 Facility, dated December 20, 2001. Based on this recent sampling, it is proposed that additional groundwater sampling of TMW-16 is not necessary as part of the well closure effort. The laboratory analytical results of the September 2002 sampling event will be reported in the well closure report.
- 4. Well Closure TMW-16 will be closed by pumping bentonite grout under pressure into the well casing and filter pack. The volume of bentonite grout pumped into the well will be greater than or equal to the volume of the casing, screen, and filter pack volume. The upper ten feet of the well casing will be over-drilled using a hollow-stem auger of a diameter larger than the initial borehole and cement seal. The top ten feet of the borehole will then be backfilled with granular bentonite to allow for site redevelopment excavation and grading. Well closure work will be performed by a California-licensed well contractor and under the oversight of a California-licensed professional engineer or registered geologist. Following well closure, a letter report will be submitted to the RWQCB documenting the well closure activities by January 31, 2002.

Wastes generated by the well closure process will be containerized and profiled for subsequent disposal.

Haley & Aldrich's Site-Specific Health & Safety Plan (SHSP) dated June 8, 2001 will be used for on-site personnel performing the well closure activities. The SHSP has been previously submitted to the RWQCB.

Should you have any questions concerning the contents of this memorandum or require additional information, please contact either of the undersigned.

Sincerely yours, Haley & Aldrich, Inc.

Robert L. Manriquez, R.G., R.E.A


Senior Geologist

Scott P. Zachary Project Manager


Attachments:


Figure 1 – Site Location Map Figure 2 – Well Location

TMW-16 Well Construction Log









	Nort		Buildir	ıg 20	-,					Boring/Well Name TMW-16		
	COM! West	PANY Hazm	at		DRILL	Scot	t Cam	obell		Project Name Boeing C-6 Facility		
ORILLING METHOD (S) CME 75, Hollow Stem Auger						BIT (S)	SIZE		·	Project Number 994001.00		
NK C	ASING		'C Schee		FROM TO FT 56.5 FROM TO FT					ELEVATION TOTAL DEPTH		
FORA"	TED C	ASING								Not Surveyed 82.5 feet Date Started Date Completed		
2" diam. PVC Schedule 40, 0.010" slot ZE AND TYPE OF FILTER PACK						56		0	76.5 FT	1/29/99 1/29/99 DEPTH TO WATER		
	Lone	star 2/1	2 Sand		FROM	54.	.5	0	82.5 FT	65 feet		
Medium Bentonite Chips						51.	.7	Ö	54.5 FT	M. Baiderman SAMPLING METHODS WELL COMPLETION		
Neat Portland Cement					FROM TO FT 0 51.7					2" x 18" California Split-Spoon		
F 1.1	MPLES		,			-				and CME dry core		
	Blows per 6	Head Space Reading (mg/L)	Depth (feet)	WELL CONSTRUCTIO	ЭN		Graphic Log	USCS Log	Muasell Color	SOIL DESCRIPTION AND DRILLING REMARKS		
					X	X .	****	X		Asphalt at surface 8" gravel/asphalt base		
	7 10 14 12		5-					ML	2.5YR 5/2	Clayey SILT with Minor Fine Sand: weak red, damp, medium stil		
×	10 11 14 18		-		\otimes	× -		ML	7.5YR 5/3	Clayey SILT with Minor Fine Sand: brown, damp, very stiff		
	11 15 17	8.2	10-							increasing sand below 12 feet 1-inch thickness of disseminated calcite at 13.5 feet		
			15-					SM	7.5YR 5/3	Fine Silty SAND: brown, 60% sand, damp, dense		
	10 14 20	12.4	20-									
X X X X X X	12 15 30	11.5	25					CL	7.5YR 5/2	Silty CLAY with Minor Fine Sand: brown, irregular calcite strings damp, hard		
	14 17 20	17.2	30-		XXXXXXXX			ML	2.5Y 5/4	Sandy SILT: light olive brown, 40% fine sand, damp, hard clayey silt interbed from 27.7 to 28 feet calcite stringers at 29.5 feet		
			35-					SM	2.5Y 6/4	Fine Silty SAND: light yellowish brown, 80% sand, damp, dense		
					X	\boxtimes						
		:∨&÷ RICH	سلحب		KX_	IX)	تكتب	1	- Maria Salah Balista			

SAMPI	l.ES							Boring/Well Name TMW-16
يدم		*	Depth (feet)	WELL CONCEDUCTION:	Graphic	USCS	Munsell	Project Name Boeing C-6 Facility
Driven Recovered Collected	Blows	Head Space Readin (mg/L)	(feet)	WELL CONSTRUCTION	Graphic Log	USCS Log	Munseli Color	Project Number 994001.00
core			-		-1.	SM	25847	Fine Silty SAND, continued hard caliche nodules from 36.5 to 37 feet
	20 25 27	8.9	40 -				2.5Y 6/2	light brownish gray
, core			45 ⁻ - -					hard calcite nodules at 47.3 feet abundant calcite cement to 50 feet
	10 14 25	13.9	50 -	Top of Seal 51.7 feet		CL	2.5Y 6/2	- Silty CLAY: light brownish gray, trace of fine sand, damp to moist, hard.
			4			CI.	0.637.571	Sandy CLAY: 30% fine sand
υ υ			55 -	Top of Filter 54.5 feet	4	SM ML	2.5Y 7/1 2.5Y 6/2	Fine Silty SAND: light gray, 80% sand Clayey SILT: light brownish gray, trace of fine sand, damp, hard
100			-	Top of Screen 56.5 feet	-	.,,,,	2.51 0/2	Clayey 3121. fight blownish gray, trace of file said, damp, hard
1			-	Top or screen 30.5 feet 7		ML	2.5Y 5/2	Fine Sandy SILT: grayish brown, 40% sand, trace of fine mica, moist, hard
						SM		grades to Silty SAND
	11	22.7	60	Depth to first water 61		ML		grades to Sandy SILT
**************************************	23		-	feet		SM ML	2.5Y 5/4	water encountered at 61 feet Fine Silty SAND and Sandy SILT: light olive brown, trace of fine mica, wet, dense
ore'			65			ML	2.5Y 5/3	Fine Sandy SILT: light olive brown, 30% fine sand clayey, moist, hard
O .			-			SM	2.5Y 5/4	Fine Silty SAND: light olive brown, 50% sand
			70 -			CL	7.5YR 5/6 7.5YR 6/1	Silty CLAY: mottled strong brown and gray, trace of fine sand, wet, hard
-			4		+	ML	2.5Y 5/4	Fine Sandy SILT: light olive brown, 35% sand, wet, hard
-			-		11111	SM	2.5Y 5/2	Fine Silty SAND: grayish brown, 65% sand, trace of fine mica, wet, dense
2.00				Bottom of Screen 76.5 feet				
			4	[4444] [4444] [4444]				
	N I S	RICE E			11:1:1:			. Boring terminated at 82.5 feet.